

Building Updates

What happened this week? Dec. 29, 2008- Jan. 2, 2009



More Paving



**Drywall
going in**



**Church
office**



Kitchen

Building Updates

What happened this week? January 5-9, 2009



Gym Drywall





Attic



**Bench in
coat room**

Building Updates

What happened this week? January 12-16, 2009



**New Doorway
to Sanctuary**







**New
Doorway to
Baptistry**



Gym



**Spackling
up high**



**Elevator
Shaft**

Building Updates

What happened this week? January 18-23, 2009



**New Doorway
to Sanctuary**

Display Case



A photograph of a narrow hallway with white walls and a light-colored floor. A silver extension ladder is positioned vertically in the center of the hallway. On the floor, there are several blue cables and some other tools. The hallway leads to a doorway at the end. The lighting is somewhat dim, and the overall scene suggests a renovation or maintenance project.

**Hallway
Painted**



**Gym
Spackled**



**New Wall
in Pastor's
Temporary
office.**



**New Wall
in Pastor's
Temporary
office.**



**Pastor's
office
painted**